AES IntelliNet 2.0 Firmware Release Notice

The below referenced firmware updates are applicable to the AES IntelliNet 2.0 subscriber units only.

AES has released two firmware updates; one for the 7707 fire subscriber, and one for the 7007 burglary subscriber. Southwest Dispatch Center urges AES installing dealers to stay current with the latest firmware updates for optimum performance of your AES IntelliNet communicators, and to resolve certain equipment performance issues. The latest AES released firmware update addresses the occasional communication failure events caused by the DACT not receiving the kissoff tone from the dialer capture module within a few seconds, and enhances the Wi-Fi SSID display shown on the display. Prior firmware updates have resolved possible dropped signals and timer test delinquencies.